

Supplies:

→Hard hat (CSA Z94.1-.05, Type 2); steel toe safety boots (CSA Z;195.02), work gloves; safety glasses (CSA Z94.3, Class 1)

→adjustable wrenches (6" and 8"); combination wire stripper; electrician's knife; flashlight; gyproc saw; hack saw; hammers (claw AND ball peen); magnetic torpedo level; 16' measuring tape; CAT-III multimeter; pliers (8" or 9"; diagonal side cutting, lineman's side cutting, needle nose, pump-slip joint); portable tool box/bag/pouch; screwdrivers (robertson #1, #2, #3, phillips #1, #2, standard-3 sizes); stud finder